

**MULLAN PASS** N47°27.41' W115°38.76' NOTAM FILE MLP.  
**(VH) (DH) VORW/DME** 117.8 MLP Chan 125 352° 50.0 NM to Libby. 6100/15E.

**GREAT FALLS**  
**H-1D, L-13B**

VOR unusable:

003°-006° byd 40 NM  
 014°-020° byd 40 NM  
 021°-031° byd 40 NM blo 18,000'  
 055°-071° byd 40 NM blo 12,000'  
 055°-071° byd 69 NM  
 060°-090° byd 20 NM blo 9,500'  
 115°-123° byd 40 NM  
 137°-139° byd 40 NM  
 206°-215° byd 40 NM  
 220°-247° byd 40 NM  
 286°-295° byd 40 NM blo 12,000'  
 296°-349° byd 40 NM

**RCO** 122.4 (BOISE RADIO)

**OPHEIM** (SØØ) 0 W UTC-7(-6DT) N48°52.00' W106°25.04'

**BILLINGS**

3264 B NOTAM FILE GTF

**RWY 16-34:** 2675X150 (TURF)

**RWY 04-22:** 1555X100 (TURF)

**RWY 22:** Road.

**RWY 10-28:** 1200X100 (TURF)

**RWY 28:** Road.

**AIRPORT REMARKS:** Unattended. No snow removal. Rwy 04-22, Rwy 10-28, Rwy 16-34 marked with red/white panels full length. Rwy 16-34, all rwy rough. Rwy 22 + 2 ft berm, 5 ft from rwy end. Rwy 22 has fence parl Rwy-10L first 372 ft of rwy. Rwy 28 has 40 ft powerline 500 ft from end of rwy.

**AIRPORT MANAGER:** (406) 724-7090

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.

## PHILIPSBURG

**RIDDICK FLD** (UØ5) 1 SE UTC-7(-6DT) N46°19.04' W113°18.31'

**GREAT FALLS**

5219 B NOTAM FILE GTF

**L-13C**

**RWY 16-34:** H3599X60 (ASPH) S-7 MIRL

**RWY 16:** Rgt t/c.

**RWY 34:** Hill.

**SERVICE:** LGT ACTIVATE MIRL Rwy 16-34—CTAF.

**AIRPORT REMARKS:** Unattended. Rwy 16-34 pavement is spalling, major crack propagation throughout. Multiple edge fractures. Rwy 16 markings faded. Rwy 34 markings faded. Sn removal intmt.

**AIRPORT MANAGER:** 406-303-1230

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE SMN.

**SALMON (VH) (DH) VORW/DME** 113.5 LKT Chan 82 N45°01.28'

W114°05.05' 010° 84.4 NM to fld. 9260/13E.

VOR unusable:

127°-135° byd 40 NM  
 136°-146° byd 40 NM blo 14,000'

